

ASSEMBLY INSTRUCTIONS
DENTYNE ICE MACHINE WALL/SIDE MOUNT

TOOLS NEEDED FOR ASSEMBLY

FLAT BLADE SCREWDRIVER
 9/16" WRENCH
 7/16" WRENCH
 SCISSOR

PARTS LIST

(PARTS LIST IN ORDER OF ASSEMBY)

	AMT	ITEM
A	1	WALL BRACKET
B	1	ASSEMBLY PLATE (BRACKET)
C	1	3/8" x 16 x 1 1/4" BOLT
D	1	3/8" LOCK WASHER
E	1	3/8" x 16 NUT
F	1	MACHINE BOTTOM PLATE
G	4	1/4" x 20 x 1/2" SCREW
H	4	1/4" x 20 LOCK WASHER
I	4	1/4" x 20 NUT
J	1	COIN BOX
K	1	VENDING MACHINE
L	1	VENDING MACHINE COVER
M	1	COVER GASKET
N	1	KEY
O	1	DECALS

ASSEMBLY

IMPORTANT DETERMIN LOCATION OF MACHINE & MOUNT WALL BRACKET ACCORDINGLY TO (B) ASSEMBLY PLATE.

ASSEMBLE PLATE (B) TO PLATE (F) & ENSURE THAT SCREWS ARE ON TOP SIDE OF PLATE AS SHOWN.

PLACE COIN BOX (J) OVER THREADED ROD ON TOP OF PLATE ASSEMBLE WITH HIGH END ON LEFT SIDE.

ASSEMBLE COVER GASKET (M) TO UNDERSIDE OF VENDING MACHINE COVER (L) BY REMOVING PAPER FROM GASKET AND STRETCHING AND FITTING TO STAY WITHIN OUTSIDE EDGES. CUT TO SIZE WITH SCISSOR.

DECALS (4)

DENTYNE ICE® .25¢

PLACE INSIDE THE CLEAR PLASTIC TOP FACING FRONT


DENTYNE ICE® (2 Decals)

PLACE INSIDE THE CLEAR PLASTIC TOP RIGHT AND LEFT SIDES

NUTRITIONAL LABEL

PLACE ON RIGHT OR LEFT SIDE OF THE BLUE LOWER SECTION OF MACHINE

*** First remove cover with key, lift machine up from bottom plate to expose coin box.**



Use the included hex wrench to tighten the two black hex screws inside the bottom of machine. These screws may become loose over time.

ASSEMBLY INSTRUCTIONS
DENTYNE ICE MACHINE WALL/SIDE MOUNT

PICTURES

